All yearly reports

# VINAYAKA ENTERPRISES

**BOREWELL COMPLETION REPORT**

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1121

Date : 18/04/24.

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Sattilite Town Sub Division BBMP Blore -64

2. Well Location : No- 2, BANDE MARAMMA, Srinivasapura

3. Total Well Depth / Drilled in Ft. : 1300ft

4. Casing Erected in Ft. :

5. Water Struck at the Depth of : 1300ft

6. Total Yield (Measuring method "V" Norch : 6½" / Inches on "V" Norch)

7. Formation of Soil/Wel Water Condition : Boulders/Silt/Loose Soil/Clear ✓

8. At the Depth of : 1300ft

9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied/Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature ABB Yvnk

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

For VINAYAKA ENTERPRISES

Manager / Proprietor

A.E.E.

Smt. Kavitha Singh
Near Gangamma Temple,
Malleshwaram, Bangalore - 03
Water Diviner

**BOREWELL COMPLETION REPORT**

# VINAYAKA ENTERPRISES
**Borewell Drilling Contractors**

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

: 1127

Date : 18/04/24

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite town Sub Division BBMP Blore - 64

2. Well Location : Kenchenahalli Yelahanka

3. Total Well Depth / Drilled in Ft. : 1250

4. Casing Erected in Ft. : 280 - 350

5. Water Struck at the Depth of : 1250

6. Total Yield (Measuring method "V" Norch : 6 4 / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ✓

8. At the Depth of : 1250

9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

A.E.E.

Water Divine

A 67998

**BOREWELL COMPLETION REPORT**

# VINAYAKA ENTERPRISES

**Borewell Drilling Contractors**

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1124

Date : 07/04/24

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite Town Sub Division BBMP Blore - 64

2. Well Location : ISRO layout Rajankunte Yelahanka

3. Total Well Depth / Drilled in Ft. : 1000

4. Casing Erected in Ft. : 250

5. Water Struck at the Depth of : 1000

6. Total Yield (Measuring method "V" Norch : 6" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ✓

8. At the Depth of : 1000

9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

[signatures]

For VINAYAKA ENTERPRISES

[signature]

Party's Signature

Manager / Proprietor

A.E.E.

Malleshwaram, Bangalore - ...

Water Diviner

**BOREWELL COMPLETION REPORT**

# VINAYAKA ENTERPRISES

**Borewell Drilling Contractors**

**Mobile : +91 9342202932 / 9343202932**

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1125 Date : ____________

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite Town Sub Division BBMP Blore-64

2. Well Location : Sai layout ISRO Layout Rajankunte YNK

3. Total Well Depth / Drilled in Ft. : 1000

4. Casing Erected in Ft. : 280

5. Water Struck at the Depth of : 1000

6. Total Yield (Measuring method "V" Norch : 6" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ✓

8. At the Depth of : 1000

9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

[signature]

Party's Signature Manager / Proprietor

[signature] A.E.E.

Malleshwaram, Bangalore - 03

[signature]

Water Diviner

**BOREWELL COMPLETION REPORT**

# VINAYAKA ENTERPRISES

**Borewell Drilling Contractors**

**Mobile : +91 9342202932 / 9343202932**

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1123

Date : 26/03/24

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite Town Sub Division BBMP Blore -64
2. Well Location : Nagenahalli Near Overhead Tank Rajanukunte YNK
3. Total Well Depth / Drilled in Ft. : 1200
4. Casing Erected in Ft. : 250
5. Water Struck at the Depth of : 1200
6. Total Yield (Measuring method "V" Norch : 6" / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ✓
8. At the Depth of : 1200
9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

A.E.E.

Water Diviner

A 67998

**VINAYAKA ENTERPRISES**
Borewell Drilling Contractors

**BOREWELL COMPLETION REPORT**

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1129

Date : 30/04/24.

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite town Sub Division BBMP Blore-64
2. Well Location : Jyothinagara Sambram College
3. Total Well Depth / Drilled in Ft. : 1300
4. Casing Erected in Ft. : 350
5. Water Struck at the Depth of : 1300
6. Total Yield (Measuring method "V" Norch : 6½" / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ✓
8. At the Depth of : 1300
9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

A.E.E.

Near Gangamma Temple, Malleswaram, Bangalore - 03

Smt. Kavitha Singh

A 67998

Smt. Kavitha Singh

**BOREWELL COMPLETION REPORT**

# VINAYAKA ENTERPRISES

**Borewell Drilling Contractors**

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1132

Date : 08/04/24

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite town Sub Division BBMP Blore-64
2. Well Location : Sai Layout Isro layout Rajanukunte YNK
3. Total Well Depth / Drilled in Ft. : 1000
4. Casing Erected in Ft. : 250
5. Water Struck at the Depth of : 1000
6. Total Yield (Measuring method "V" Norch : 6" / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ✓ (Loose Soil)
8. At the Depth of : 1000
9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump ✓ (Submersible)

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

[signature]

Party's Signature

For VINAYAKA ENTERPRISES

[signature]

Manager / Proprietor

A 67998

# VINAYAKA ENTERPRISES

**Borewell Drilling Contractors**

**BOREWELL COMPLETION REPORT**

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1122

Date : 26/04/24

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite Town Sub Division BBMP Blore 64
2. Well Location : Near ~~Swami~~ Mahathma Temple, Subhashnagar Park
3. Total Well Depth / Drilled in Ft. : 1250
4. Casing Erected in Ft. : 300
5. Water Struck at the Depth of : 1280
6. Total Yield (Measuring method "V" Norch : 6" / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ✓
8. At the Depth of : 1250
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump ✓

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

A.E.E.